

Inputs/Outputs connectors

<i>HE10 14 pts</i>	<i>SUBD 15pts</i>	<i>Inputs/Outputs</i>
1	1	Analog Output Gate #1
2	9	Analog Output Gate #2
3	2	Analog Output Gate #3
4	10	TTL alarm Output Gate #1
5	3	TTL alarm Output Gate #2
6	11	TTL alarm Output Gate #3
7	4	GND
8	12	Coder #1 φA (Input)
9	5	Coder #1 φB (Input)
10	13	Coder #2 φA (Input)
11	6	Coder #2 φB (Input)
12	14	Reserved
13	7	Input Synchronize
14	15	GND
	8	VCC (5V USB)